M.C.D.	
South Zone	18
Najafgarh Zone	2
Narela Zone	26
Rohini Zone	29
D.D.A.	
Central Zone	3
West Zone	35
Rohini Zone	113
North Zone	12
East Zone	88
Sout West Zone	22

Work done by BHEL

4293. SHRI GOVINDA CHANDRA MUNDA:Will the PRIME MINISTER be pleased to state:

(a) whether due to poor quality of work done by BHEL at Tenughat Thermal Power Project, Lalpania Dist., Bokaro, the structures of (1) Cement shed (2) C.W.Duct (3) M.C.C. Room (4) Boundry Wall from coordunate 15A+6/18B+50 failed and claims have been taken from insurance company;

(b) the details of various complaints made by GM, TVNL to BHEL in this regard;

(c) the details of enquiries ordered into the matter and the findings thereof; and

(d) the details of disciplinary action taken against those found guilty?

THE MINISTER OF STATE IN THE MINISTRY OF INDUSTRY (SHRI P.K. THUNGON): (a) to (d). No structure failed due to poor quality of work. However, Insurance claims have been lodged in respect of following structures which failed due to reasons given below:

Cement Storage shed

One Gable end walls of temporary cement storage shed which was under construction, collapsed due to cyclone at site.

C.W. Duct

There is only one case of earth caving due to heavy rain as C.W. Duct was constructed in filled-up area.

Motor control Centre(M.C.C.)

Some cracks developed in this building due to uneven settlement of soil.

Boundry wall

A portion of the boundry wall collapsed due to accumulation of water. A letter was received from GM, TVNL regarding collapse of the boundry wall. The matter was jointly investigated by BHEL and TVNL engineers. It was established that the collapse was due to water thrust and not due to poor quality of work.

In view of above no disciplinary action is called for.

List of plots sent by DDA to MCD Regarding Unauthorised Constructions

4294. SHRI ARJUN SINGH YADAV:Will the Minister of URBAN DEVELOPMENT be pleased to state:

(a) whether DDA had forwarded a list of